

govt ITI HN PURA

ITI Quiz - 06-Feb-2026 09:49 AM

Q. ID: ITISKILL322279 | February 2026

36.84% 14 / 38

Student Name	GANESH	Access Code	5080
Attempt No.	#1	Completion Time	10:40 AM
Rank	#10	Total Questions	38

14 SCORE

38 MAX MARKS

14 CORRECT

24 INCORRECT

Answer Review

Q1 **INCORRECT** Which material is used to make radius gauge?

A. Cast steel

B. Tool steel ☐

C. Hardened steel ☐

D. Stainless steel

Q2 **INCORRECT** What is the name of gauge used to check the radius

A. Radius gauge ☐

B. Fillet gauge

C. Plug gauge

D. Feeler gauge ☐

Q3 **INCORRECT** Which cutting tools have highest cutting efficiency?

A. Mild steel

B. High carbon steel ☐

C. High speed steel

D. Carbide ☐

Q4 **CORRECT** Which is the cheapest tool material?

A. High carbon steel ☐

B. High speed steel

C. Carbide

D. Diamonds

Q5 **CORRECT** Which is a non-metallic tool material?

A. High carbon steel

B. Diamonds ☐

C. Stellite

D. Carbide

Q6 **CORRECT** Which one is chief constituent of ferrous tool material?

A. Iron ☐

B. Tungsten

C. Vanadium

D. Carbon

Q7 **INCORRECT** Which one is example of ferrous tool material?

A. High carbon steel ☐

B. Carbide tool

C. Stellite

D. Diamonds ☐

Q8 **INCORRECT** What is the value of tool life index for a cemented carbide tip to machine cast iron component?

A. 0.1 ☐

B. 0.125

C. 0.2 ☐

D. 0.128

Q9 **INCORRECT** What is the tool life index of cemented carbide tool for turning high carbon high chromium die steel?

A. 0.15 ☐

B. 0.2 ☐

C. 0.4

D. 0.35

Q10 **INCORRECT** What does the letter Y stands in the formula $d = Y \sqrt[2]{s+r}$ in taper measurement?

A. Diameter over rollers at small end ☐

B. Diameter over rollers at big end ☐

C. Radius of the roller

D. Distance from the centre of the roller to the end of the component

Q11 **CORRECT** What does the letter 's' stands in the equation $d = Y - 2(s + r)$ in taper measurement?

- A. Diameter over the roller at large end
- B. Diameter over the rollers at small end
- C. Radius of the rollers
- D. Distance from the centre of the roller to the end of the component ☒

Q12 **CORRECT** How many precision rollers required for measuring angle of tapered component?

- A. 1
- B. 2 ☒
- C. 3
- D. 4

Q13 **INCORRECT** What is the recommended cutting speed for turning mild steel using H.S.S tool?

- A. 25-40 m/min
- B. 35-70 m/min
- C. 40-70 m/min ☐
- D. 35-50 m/min ☒

Q14 **INCORRECT** What is the recommended feed rate for turning cast iron (grey) using H.S.S tool?

- A. 0.08-0.03 mm/rev
- B. 0.2-1.00 mm/rev ☐
- C. 0.2-1.5 mm/rev
- D. 0.15-0.7 mm/rev ☒

Q15 **INCORRECT** How the cutting speed is expressed?

A. Foot/min

B. Meter/sec

C. Meter/min ☒

D. Revolution/min ☐

Q16 **INCORRECT** What is the recommended cutting speed for aluminium using H.S.S tool?

A. 70 m/min - 100 m/min ☒

B. 50 m/min - 80 m/min ☐

C. 35 m/min - 50 m/min

D. 25 m/min - 40 m/min

Q17 **CORRECT** How much percentage of cutting speed could be increased by using super HSS tools?

A. 5% to 10%

B. 10% to 15%

C. 15% to 20% ☒

D. 20% to 25%

Q18 **CORRECT** Which gauge is to be selected for checking the corner radius of the job?

A. Radius gauge ☒

B. Fillet gauge

C. Feeler gauge

D. Plug gauge

Q19 **CORRECT** Where the follower is fixed to produce from turning?

A. Tool part

B. Top slide

C. Cross slide ☒

D. Tail stook

Q20 **INCORRECT** Which gauge is used to check the radius formed at the steps of component?

A. Fillet gauge ☒

B. Radius gauge

C. Feeler gauge ☐

D. Plug gauge

Q21 **INCORRECT** What is the term the distance moved by the tool along the work for each revolution?

A. Speed

B. Feed ☒

C. Cutting speed

D. Depth ☐

Q22 **INCORRECT** What are the possible surface that can be produced by form turning?

A. To generating concave and convex profile ☒

B. To generating cylindrical surface

C. To generate conical surface

D. To generate flat surface ☐

Q23 **CORRECT** Which type of tool is suitable to produce form surface in mass production activities?

A. Using carbide tipped form tool ☒

B. High carbon steel tool ☐

C. High speed steel cutting tool ☐

D. Using single point cutting tool ☐

Q24 **INCORRECT** What factor is important in free hand form turning?

A. Unskilled labour ☐

B. Skilled labour ☒

C. Sharp tool ☐

D. High speed ☐

Q25 **CORRECT** Which type of jig is used to hold thin and soft parts?

A. Plat jig ☐

B. Channel jig ☐

C. Sandwich jig ☒

D. Trunnion jig ☐

Q26 **INCORRECT** Which type of jig is used for large awkward shaped piece part is to drilled in many directions?

A. Plate jig ☐

B. Post jig ☐

C. Table jig ☐

D. Trunnion jig ☒

Q27 **CORRECT** Which is the device that can hold, locate and guide the tool?

A. Jig ☒

B. Fixture ☐

C. Chuck ☐

D. Collet chuck ☐

Q28 **CORRECT** What is the advantage of jig?

A. It holds the job ☐

B. Hold and locate the work ☐

C. Hold, locate and guide the tool ☒

D. Cost is very low ☐

Q29 **INCORRECT** What is the special benefit of using a fixture?

A. Slower rate of production ☐

B. Skilled worker required ☐

C. Faster rate of production ☒

D. Suitable for small batch production ☐

Q30 **INCORRECT** Which gauge is used to position the cutter before cutting in milling fixture?

A. Feeler gauge ☒

B. Radius gauge ☐

C. Fillet gauge ☐

D. Screw pitch gauge ☐

Q31 **INCORRECT** Calculated the rpm of spindle if cutting speed V is 120m/min and the diameter D of the job is 50 mm?

A. 500 rpm

B. 764 rpm ☒

C. 856 rpm ☐

D. 975 rpm

Q32 **CORRECT** Calculate the spindle speed to turn a 40mm dia M.S rod using a cemented carbide tool if cutting speed is 92mm/min?

A. 508 rpm

B. 685 rpm

C. 731 rpm ☒

D. 950 rpm

Q33 **INCORRECT** Calculate the length of metal passing by cutting tool in one revolution if the diameter of work is 75mm and cutting speed is 120m/min.

A. 235.5 mm ☒

B. 295.7 mm

C. 365.3 mm ☐

D. 485.7 mm

Q34 **INCORRECT** Find out the R.P.M of spindle for a 50mm bar (D) and cutting speed is 25m/min.

A. 100rpm ☐

B. 159rpm ☒

C. 168rpm

D. 250rpm

Q35 **INCORRECT** Which type of jig locates the piece part from its face?

A. Plate jig ☐

B. Post jig ☐

C. Table jig ☒

D. Solid jig ☐

Q36 **INCORRECT** What defect may occur during grinding a form tool cutting edge?

A. Form tool getting broken ☐

B. Shape of the form gets altered ☒

C. Clearance angle changed ☐

D. Thickness of the tool reduced ☐

Q37 **CORRECT** What will happen to the tool life if the spindle is running higher speed?

A. Less ☒

B. More ☐

C. Medium ☐

D. Very less ☐

Q38 **INCORRECT** What is the effect, if the cutting speed is more than the recommended?

A. Reduce the tool life ☒

B. Better finish ☐

C. Accurate dimension ☐

D. Normal tool life ☐