



19. Which file is used for filing wood?

- A) Rasp cut file
- B) Smooth file
- C) Single cut file
- D) Double cut file

20. Which material is used to clean oil and grease on the floor?

- A) Saw dust
- B) Water

C) Air

D) Cotton waste

21. Which is the point angle of a twist drill used for zinc alloy?

- A) 125 Degree
- B) 100 Degree
- C) 118 Degree
- D) 90 Degree