

Gurukula iti kollegala

EM

Q. ID: ITISKILL07829P | June 2026

24.00% 6 / 25

Student Name	Kendaganna swamy	Access Code	4759
Attempt No.	#1	Completion Time	11:19 AM
Rank	#20	Total Questions	25

6 SCORE

25 MAX MARKS

6 CORRECT

19 INCORRECT

Answer Review

Q1 **INCORRECT** Which bearing is supporting the shaft of moving coil assembly in a PMMC instrument?

A. Steel bearings

B. Bush bearings ☐

C. Jewelled bearings ☐

D. Gun metal bearings

Q2 **INCORRECT** What is the full form of the abbreviation PMMC meter?

A. Parallel Magnet Moving Coil meter

B. Position Magnet Moving Coil meter ☐

C. Principle Magnet Moving Coil meter

D. Permanent Magnet Moving Coil meter ☐

Q3 **INCORRECT** Which type of wave is generated in Schmitt trigger circuit?

A. Sine wave

B. Square wave ☒

C. Saw tooth wave ☐

D. Triangular wave

Q4 **CORRECT** Which electrode controls brightness of the image on the screen of oscilloscope?

A. Anode

B. Cathode

C. Control grid ☒

D. Focussing electrode

Q5 **INCORRECT** Which band is used for UHF in International Telecommunication System?

A. Band 4

B. Band 6

C. Band 9 ☒

D. Band 11 ☐

Q6 **INCORRECT** Which parameter is measured by a multimeter?

A. Voltage ☒

B. Energy

C. Frequency

D. Time duration ☐

Q7 **INCORRECT** Which torque is used in PMMC meter movement?

A. Low torque

B. High torque ☐

C. Moderate torque ☐

D. Insufficient torque

Q8 **INCORRECT** Which instrument used to measure resistance, capacitance and inductance?

A. LCR bridge ☐

B. Wein bridge

C. Kelvin bridge

D. Wheatstone bridge ☐

Q9 **INCORRECT** Find the value of shunt resistance required for 1 mA meter to extend the range and measure 10 mA ($R_M = 27 \text{ Ohm}$) ?

A. 1 Ohm

B. 2 Ohms

C. 3 Ohms ☐

D. 4 Ohms ☐

Q10 **INCORRECT** In which arrangement the high value of resistor is connected to extend the range of voltmeter?

A. Star

B. Delta ☐

C. Series ☐

D. Parallel

Q11 **CORRECT** In which analog meter the battery is provided?

A. Ammeter

B. Voltmeter

C. Ohm meter ☒

D. Watt meter

Q12 **INCORRECT** Which function control in CRO, adjust the trace sharper?

A. Focus ☒

B. Intensity

C. Time/Div trigger ☐

D. Amplitude (V/Div)

Q13 **INCORRECT** Which meter uses a moving coil for measurement?

A. LCR meter ☐

B. PMMC meter ☒

C. MI repulsion type

D. MI attraction type

Q14 **INCORRECT** Which parameter is used in the working of moving coil meter?

A. Spring control

B. Stray magnetic fields

C. Eddy current damping ☐

D. Permanent magnetic fields ☒

Q15 **INCORRECT** What is the advantage of using digital multimeter?

- A. Accuracy ☐
- B. Linear scale
- C. Easy portability
- D. Logarithmic scale ☐

Q16 **INCORRECT** Which meter movement is not affected by stray magnetic fields?

- A. PMMC meter ☐
- B. Thermo couple meter
- C. MI meter - attraction type ☐
- D. MI meter - Repulsion type

Q17 **INCORRECT** Which characteristics enable the deflection of pointer in the attraction type moving iron meter?

- A. Weight of the soft iron pieces
- B. Deflection is inversely proportional to current
- C. Deflection is independent of current direction ☐
- D. Deflecting and controlling torques are ☐

Q18 **CORRECT** Which band of frequency is used for RADAR in frequency spectrum allotted by the International Telecommunication Union (ITU)?

- A. ITU band - 4
- B. ITU band - 6
- C. ITU band - 8
- D. ITU band - 10 ☐

Q19 **INCORRECT** Which control is used in repulsion type moving iron instrument to keep the pointer at zero position?

A. Spring control ☐

B. Air damping control ☐

C. Magnetic repulsion control ☐

D. Magnetic attraction control ☐

Q20 **CORRECT** Which frame is used for winding the coil of PMMC meter?

A. Steel frame ☐

B. Wooden frame ☐

C. Ceramic frame ☐

D. Aluminium frame ☐

Q21 **INCORRECT** What is the purpose of damping torque in PMMC meter?

A. Control the pivot point ☐

B. Control the jewel bearing ☐

C. Control the magnetic field ☐

D. Control the swinging of the coil ☐

Q22 **INCORRECT** Why the soft iron pieces in the moving iron meter is tongue shaped?

A. To generate heat ☐

B. To damp the oscillations ☐

C. To achieve uniformity of scale ☐

D. To produce magnetic attraction ☐

Q23 **CORRECT** How the sensitivity of voltmeter is determined?

- A. FSD current
- B. Meter coil resistance
- C. Ohms per volt rating ☒
- D. Maximum voltage measurement

Q24 **INCORRECT** What is the name of the procedure carried out to ensure the trustworthy standards of the measuring instrument?

- A. Calibration ☒
- B. Range test
- C. Re-alignment ☐
- D. Testing standards

Q25 **CORRECT** How the accuracy of amplitude and frequency measured by CRO is checked?

- A. By sine wave signal
- B. By function generator
- C. By complex wave form
- D. By built-in calibration signal ☒